



Clearance Inspection Checklist	
<b>Job Number</b>	16725
<b>Project Name</b>	DC Multiple Projects
<b>Project Address:</b>	930 Tacoma Ave South
<b>Project area in facility:</b>	930 building, 5th floor - suite 534
<b>Client:</b>	Pierce County Facilities Management
<b>Client Job Number:</b>	
Visual	
<b>Visual Date and Time</b>	03-Oct-2019 03:25
<b>Area Cleaned &amp; Wet Wiped?</b>	Yes
<b>Removal surfaces clean?</b>	Yes
<b>First layer of floor removed?</b>	N/A
<b>Lock down tinted?</b>	N/A
<b>Containment encapsulated?</b>	N/A
<b>Hard to reach/see areas inspected?</b>	Yes
<b>Repeat clean if Necessary</b>	No
<b>Visual Notes/Comments</b>	All abated straight run pipe insulation has been fully abated, pipe are free of all debris.
<b>Technician conducting visual:</b>	Tyler Sadler
<b>Technician signature</b>	
Air Clearance	
<b>Air Clearance -- Date and Time</b>	03-Oct-2019 05:24
<b>Clearance Air Sample Number(s):</b>	103-01 through 103-03
<b>Clearance Air Sample Result(s) (Fibers/cc):</b>	F/CC=<0.004
<b>Encapsulant applied and dry before air sampling?</b>	N/A
<b>Elapsed time since encapsulation:</b>	N/A
<b>Clearance below specified level?</b>	Pass
<b>Technician reading air clearance:</b>	Tyler Sadler
<b>Email Report to:</b>	

Area Photo:

