



Clearance Inspection Checklist	
<b>Job Number</b>	16725
<b>Project Name</b>	DC Multiple Projects
<b>Project Address:</b>	925 Tacoma Ave South
<b>Project area in facility:</b>	925 building, west entryway
<b>Client:</b>	Pierce County Facilities Management
<b>Client Job Number:</b>	
Visual	
<b>Visual Date and Time</b>	25-Sep-2019 01:20
<b>Area Cleaned &amp; Wet Wiped?</b>	Yes
<b>Removal surfaces clean?</b>	Yes
<b>First layer of floor removed?</b>	Yes
<b>Lock down tinted?</b>	No
<b>Containment encapsulated?</b>	Yes
<b>Hard to reach/see areas inspected?</b>	Yes
<b>Repeat clean if Necessary</b>	No
<b>Visual Notes/Comments</b>	Encapsulation being applied post visual clearance.
<b>Technician conducting visual:</b>	Tyler Sadler
<b>Technician signature</b>	
Air Clearance	
<b>Air Clearance -- Date and Time</b>	26-Sep-2019 07:30
<b>Clearance Air Sample Number(s):</b>	926-01
<b>Clearance Air Sample Result(s) (Fibers/cc):</b>	F/CC=<0.004
<b>Encapsulant applied and dry before air sampling?</b>	Yes
<b>Elapsed time since encapsulation:</b>	16 hours
<b>Clearance below specified level?</b>	Pass
<b>Technician reading air clearance:</b>	Tyler Sadler
<b>Email Report to:</b>	

Area Photo:

